

HAB. B-777 AIRPLANE GENERAL, EMER EQUIP, DOORS, WINDOWS

- 1 What must the aircrew do if using the portable halon fire extinguishers on the flight deck?
 - A) All flight crew members must wear oxygen masks and use 100% oxygen with emergency selected.
 - B) Leave the flight deck. Halon is toxic in confined areas.
 - C) Avoid skin contact. Halon causes skin blisters.
 - D) Nothing. Halon is not hazardous.

- 2 The TAXI Light Switch is turned ON. Which statement about the Taxi Lights is most correct?
 - A) The Taxi Lights illuminate when the nose landing gear is down and locked and point in the direction of the nose wheels.
 - B) The Taxi lights may illuminate at all times.
 - C) The Taxi Lights illuminate and point in the direction of the nose wheels.
 - D) The Taxi Lights illuminate when the nose landing gear is down and locked and point straight ahead of the airplane.

- 3 When the Door Select Lever is in the red armed position, which of the following is correct?
 - A) The slide bar is attached to the floor fittings and the door is selected for counterbalance emergency opening.
 - B) The slide bar is not attached to the floor fittings and the door is selected for normal operation.
 - C) The slide bar is attached to the floor fittings and the door is selected for pneumatic emergency operation.
 - D) The slide bar is attached to the floor fittings and the door is selected for electrical emergency operation.

- 4 Is it possible to check at a door if the girt bar is attached to the floor fittings?
 - A) No, the girt bar indicator is not visible.
 - B) Yes, the girt bar indicator flags are colored black.
 - C) No, the girt bar indicator flags only indicate if the slide is usable.
 - D) Yes, the girt bar indicator flags are colored yellow.

- 5 If you open a passenger entry door that is in the red armed mode from the inside and the slide/raft does not inflate automatically, which of the following action must you perform?
 - A) Pull the manual inflation handle located on the cabin side wall.
 - B) Pull the manual inflation handle located on the girt.
 - C) Use the red manual inflation tube.
 - D) Redirect passengers to another usable exit.

- 6 What action reactivates the boom microphone following use of the flight crew oxygen system?
 - A) The reset test switch must be pushed with the left oxygen panel doors in any position to reactivate the boom microphone and deactivate the mask microphone.
 - B) No action is required, the boom microphone resets itself when oxygen flow stops.
 - C) The reset test switch must be pushed with the left oxygen panel door closed to reactivate the boom microphone and deactivate the mask microphone.
 - D) The reset test switch must be pushed with the left oxygen panel door open to reactivate the boom microphone and deactivate the mask microphone

HAB. B-777 AIR SYSTEMS

- 1 What happens when the BULK CARGO TEMPERATURE selector is positioned to HIGH?
 - A) The compartment temperature is automatically kept at approximately 7 degrees C or 45 degrees F.
 - B) The compartment temperature is automatically kept at approximately 21 degrees C or 70 degrees F.
 - C) The compartment temperature is automatically kept at approximately 21 degrees or 70 degrees F and the bulk cargo compartment ventilation fan operates continuously.
 - D) The bulk cargo compartment ventilation fan operates continuously.

- 2 Which statement is not correct about the equipment cooling override mode?
 - A) The mode is automatically selected in flight when both equipment cooling fans fail.
 - B) The mode is selected automatically in flight when low airflow is detected.
 - C) The EICAS message EQUIP COOLING OVRD is displayed.
 - D) It is automatically selected when smoke is detected in the Forward Cargo Compartment.

- 3 During climb, what parameter(s) schedule cabin altitude?
 - A) A constant pressure differential.
 - B) Takeoff and landing field elevation.
 - C) Airplane climb rate and flight plan cruise altitude.
 - D) Airplane flight altitude.

- 4 What is the normal position of the forward outflow valve after landing?
 - A) 30 degrees open.
 - B) In transit.
 - C) Full open.
 - D) Full closed.

- 5 During preflight, what are the normal indications of the L ENG and R ENG BLEED AIR switches?
 - A) Switches off, with OFF lights illuminated.
 - B) Switches off, with OFF lights extinguished.
 - C) Switches ON, with OFF lights extinguished.

- 6 The normal inflight configuration of the bleed air isolation valves is?
 - A) All valves closed.
 - B) All valves open.
 - C) Left and right valves closed; center valve open.
 - D) Left and right valves open; center valve closed

HAB. B-777 ANTI-ICE, RAIN

- 1 Why are the wipers never operated on a dry windshield?
 - A) Windshield scratching may occur.
 - B) The wiper blades will be ruined.
 - C) The wiper motor may burn out.
 - D) Bugs will be smeared all over the window.

- 2 What does the EICAS advisory message WINDOW HEAT indicate?
 - A) The windows are using back up heat.
 - B) The backup window heat system is inoperative.
 - C) A single overheat or fault has occurred .
 - D) Two or more window heat faults have occurred.

- 3 What position should the ENGINE ANTI-ICE selectors be in for taxiing in icing conditions?
 - A) Either AUTO or ON.
 - B) AUTO.
 - C) OFF.
 - D) ON.

- 4 What position should the WING ANTI-ICE selector be in for taxiing in icing conditions?
 - A) ON.
 - B) OFF.
 - C) Either AUTO or ON.
 - D) AUTO.

- 5 What action should you take if the EICAS advisory message ICE DETECTORS is displayed?
 - A) Operate engine and wing anti ice systems manually for remainder of flight.
 - B) Turn all ANTI-ICE selectors to ON then back to AUTO to reset the system.
 - C) Turn all ANTI-ICE selectors OFF for remainder of flight and avoid icing.
 - D) Operate engine and wing anti ice systems manually when icing conditions are encountered.

HAB. B-777 AUTOMATIC FLIGHT

- 1 What is the sequence of steps to use FLCH to descend to 5000 feet at 240 kts?
 - A) Set 5000 feet in the ALTITUDE window, push FLCH switch, then set 240 kts in the IAS/MACH window.
 - B) Set 240 kts in the IAS/MACH window, push FLCH switch, then set 5000 feet in the ALTITUDE window.
 - C) Set 280 feet in the ALTITUDE window, push FLCH switch, then set 500 kts in the IAS/MACH window.
 - D) Push FLCH switch, set 5000 feet in the ALTITUDE window, then set 240 kts in the IAS/MACH window.

- 2 With HDG SEL engaged, what is the CORRECT sequence of steps to turn right to track 150 degrees using the TRK SEL mode?
 - A) Push HDG/TRK HOLD switch, then rotate the HDG/TRK selector to the right to set 150 in the HDG/TRK window and then press HDG/TRK reference switch.
 - B) Push the LNAV reference switch, verify LNAV on the FMA, then rotate the HDG/TRK selector to the right to set 150 in the HDG/TRK window.
 - C) Push the HDG/TRK reference switch, verify TRK SEL on the FMA, then rotate the HDG/TRK selector to the right to set 150 in the HDG/TRK window.
 - D) Rotate the HDG/TRK selector to the right to set 150 in the HDG/TRK window then press the HDG/TRK reference switch.

- 3 When V/S shows in the V/S-FPA window, what are the correct steps to make a 2.6 degree FPA descent?
 - A) Push VS/FPA switch only.
 - B) Set new altitude, push VS/FPA reference switch, push VS/FPA switch and set 2.6 degree flight path angle.
 - C) Push VS/FPA switch, set 2.6 degree flight path angle, set new altitude.
 - D) Push V/S-FPA reference switch, set new altitude, push VS/FPA switch, set 2.6 degree flight path angle.

- 4 What switch resets the autothrottle system and also cancels the AUTOTHROTTLE DISC message?
 - A) Master caution switch.
 - B) Autothrottle disconnect switch.
 - C) Autopilot disconnect switch.
 - D) CANC/RCL switch.

- 5 What will the autopilot do if you override the control column?
 - A) Engage in TRK HOLD and FPA.
 - B) Cause both roll and pitch modes to fail.
 - C) Disengage.
 - D) Engage in HDG HOLD and V/S.

HAB. B-777 COMMUNICATIONS

- 1 What happens if you push the CAB transmitter select switch twice within one second?
- A) A pre-recorded message is sent to a pre-selected cabin station.
 - B) A conference call is initiated with all cabin stations.
 - C) Nothing, the second push cancels the selection.
 - D) A priority call is placed to a pre-selected cabin station.
- 2 Which method does not allow the flight crew to make a PA announcement to all areas of the cabin?
- A) Push the PA transmitter select switch on the audio control panel and key any MIC switch.
 - B) Using the flight deck handset, push the handset PA Push To Talk switch.
 - C) Push the CAB transmitter select switch on the audio control panel, then enter the appropriate dial code using the CDU keypad, then key any MIC switch
 - D) Push the FLT interphone transmitter switch twice within one second.
- 3 Which method of providing a CABIN READY signal to the flight deck is not a normal use of the cabin interphone system?
- A) By a CABIN READY interphone signal.
 - B) By a CABIN READY EICAS communications message.
 - C) By a CABIN ALERT EICAS communications message.
 - D) Voice message from a cabin interphone location.
- 4 When an HF transmitter is keyed after a frequency change the antenna tunes. While the antenna is being tuned, a tone can be heard through the audio system. How much time must be allowed for the antenna to tune?
- A) Tuning takes a maximum of 15 seconds.
 - B) Tuning takes a maximum of 5 seconds.
 - C) Tuning takes a maximum of 10 seconds.
 - D) Tuning takes a maximum of 20 seconds.
- 5 Which statement about the Offside Tuning Light is not correct?
- A) The radio tuning panel is being used to tune a radio not normally associated with this radio tuning panel.
 - B) The center Radio Tuning panel is normally associated with VHF C and HF C.
 - C) The right Radio Tuning panel is normally associated with VHF R and HF R.
 - D) The left Radio Tuning panel is normally associated with VHF L and HF L.

HAB. B-777 ELECTRICAL

- 1 What is the primary source of DC power during normal flight?
 - A) Main battery.
 - B) Transformer rectifier units.
 - C) DC generators.
 - D) APU battery.

- 2 What is the primary electrical power source for flight control system?
 - A) Main AC busses.
 - B) APU.
 - C) Permanent magnet generators.
 - D) Battery.

- 3 Which condition(s) cause the EICAS message ELEC GEN DRIVE L to display?
 - A) Generator drive oil pressure is low.
 - B) Generator drive oil temperature is high.
 - C) GENERATOR CONTROL switch selected to OFF.
 - D) Generator drive oil temperature is high or generator drive oil pressure is low.

- 4 What is the alternate source of power for the ground handling bus?
 - A) Left transfer bus.
 - B) Secondary external power.
 - C) APU.
 - D) Right transfer bus.

- 5 What happens in flight when both transfer busses become unpowered?
 - A) The APU starts automatically, regardless of the APU selector position.
 - B) No other power source is available so only the standby bus remains powered until pilot action.
 - C) The RAT powers both transfer busses.
 - D) The APU must be manually started and connected to the transfer busses.

- 6 What normally powers the 4 Transformer-rectifier units (TRUs)?
 - A) Ground service bus.
 - B) Left and right main DC bus.
 - C) APU battery.
 - D) Both AC transfer busses.

HAB. B-777 ENGINES, APU

- 1 What thrust reference mode indicates an assumed temperature derated takeoff thrust is selected?
 - A) TO 2
 - B) TO.
 - C) D-TO.
 - D) TO 1.

- 2 Where is engine oil quantity displayed?
 - A) There is no flight deck display for engine oil quantity.
 - B) The secondary engine indications.
 - C) The primary engine indications.
 - D) The status display.

- 3 What occurs if the required EEC signals are not available to operate the engines in the normal mode?
 - A) The affected engine goes to flight idle.
 - B) The Autothrottle disconnects.
 - C) Full rated thrust is automatically commanded on the affected engine.
 - D) The EEC automatically uses the alternate mode.

- 4 What does the EICAS message ENG STARTER CUTOFF L indicate?
 - A) Autostart has failed to start the left engine.
 - B) The left engine autostart switch is OFF.
 - C) The left fuel control switch is in RUN at low engine RPM with the autostart switch OFF.
 - D) The left engine start/ignition selector remains in the START position or the start valve is open when commanded closed.

- 5 Which of the following does not happen when the Fuel Control switch is placed to RUN with Autostart ON?
 - A) The EEC opens the valve and turns on the ignitor(s) when required.
 - B) The engine fuel valve is armed.
 - C) The engine ignitor(s) is/are armed.
 - D) The spar fuel valve is armed.

- 6 Which statement about the thrust reversers operation is not correct?
 - A) The amber REV indication changes to green REV when the reverser interlock is released.
 - B) Not all conditions limiting or preventing reverse thrust can be detected before reverse thrust is selected.
 - C) The reverse thrust levers can be limited from moving beyond the interlock position by conditions that limit or prevent reverse thrust.
 - D) The EICAS message ENG REV LIMITED is displayed if the reverser cannot deploy when commanded.

- 7 Which statement about the auxiliary power unit starting is correct?
 - A) On the ground, the APU can be started with no pumps operating.
 - B) During APU start on the ground, starting fuel is supplied from the center tank DC fuel pump until AC power is available.

- C) The starter engages immediately. When the air inlet door reaches full open, fuel and ignition are provided.
- D) With the APU generator switch in the OFF position, automatic APU start in the event that both AC transfer busses lose power is inhibited.

HAB. B-777 FIRE PROTECTION

1 After the FWD CARGO FIRE ARM switch has been armed, what happens when the DISCH switch is pushed?

- A) All 5 fire bottles arm and airflow around the cargo compartment is reduced.
- B) All 5 bottles discharge into the forward cargo compartment.
- C) Two rapid dump bottles discharge into the forward cargo compartment.
- D) One of the metered bottles discharges into the forward cargo compartment.

2 Which statement is true concerning a lavatory fire?

- A) An automatic sprinkler system activates if a fire is detected.
- B) There is no built-in fire extinguishing system for the lavatories.
- C) The lavatory fire extinguishing system is activated by a discharge switch on the overhead panel.
- D) An aural warning activates and a light illuminates outside the lavatory if smoke is detected.

3 What does the DET FIRE CARGO AFT EICAS message indicate?

- A) The aft cargo fire heat sensor is inoperative.
- B) A fire has been detected in the aft cargo compartment.
- C) There is a detection zone fault in the smoke detector for the aft cargo compartment.
- D) Fire detection for the aft cargo compartment is not available.

4 Which statement about about the APU Fire Detection is not correct?

- A) An APU fire warning automatically shuts down the APU.
- B) The APU compartment has dual fire detector loops.
- C) There is no APU overheat detection.
- D) The EICAS advisory message DET FIRE APU is displayed if there is an APU fire.

HAB. B-777 FLIGHT CONTROLS

1 Roll control is provided by?

- A) Ailerons, flaperons and spoilers.
- B) Slats and spoilers only.
- C) Flaperons and slats.
- D) Krueger flaps, slats and spoilers.

2 Which statement is not correct concerning stabilizer trim?

- A) Activating the stabilizer trim switches on the control wheel disengages the autopilot.
- B) As airspeed increases, trim rate decreases.
- C) The green band on the stabilizer position indicator shows the acceptable range for takeoff.
- D) You can use the pitch trim switches on the ground to set the trim.

3 What happens when the stabilizer signal is not present or is invalid?

- A) The CDU displays the VERIFY TRIM message in the scratchpad.
- B) The EICAS message STAB GREENBAND displays.
- C) The green band and the pointer are not displayed.
- D) The green band on the indicator turns amber.

4 What are the initial steps to extend the flaps using the alternate flap mode?

- A) Arm ALT FLAPS ARM switch. Select NORMAL FLAPS selector to 20.
- B) Arm ALT FLAPS ARM switch. Select ALT FLAPS selector to OFF.
- C) Push ALT FLAPS ARM switch to OFF. Select ALT FLAPS selector to EXT.
- D) Arm ALT FLAPS ARM switch. Select ALT FLAPS selector to EXT.

5 Which of the following is not correct concerning the flight control system when operating in secondary mode?

- A) Envelope protection features are NOT available.
- B) Autopilot and envelope protection are NOT available.
- C) Thrust Asymmetry is NOT available.
- D) All spoilers remain usable.

6 What does the EICAS message FLIGHT CONTROL MODE indicate?

- A) The Flap/Slat electronics units are inoperative.
- B) Flight control system faults are detected.
- C) Multiple flight control surfaces are inoperative.
- D) Flight control system is operating in the secondary mode.

7 How many spoiler panels are used as Speedbrakes?

- A) A total of 12 spoiler panels.
- B) None of the answers are correct.
- C) A total of 14 spoiler panels.
- D) A total of 10 spoiler panels.

HAB. B-777 FUEL

- 1 Which fuel pumps are used for fuel jettison?
 - A) Left and right main tank jettison pumps and the center tank jettison/override pumps.
 - B) Left and right main tank fuel pumps and the center tank override pumps.
 - C) Left and right main tank jettison pumps only.
 - D) All fuel pumps are used for fuel jettison.

- 2 Balancing fuel requires the use of:
 - A) Both crossfeed valves and both pumps in the high main tank.
 - B) Either crossfeed valve and both pumps in the high main tank.
 - C) Both crossfeed valves and both pumps in the low main tank.
 - D) Either crossfeed valve and both pumps in the low main tank.

- 3 Why does center tank fuel feed to the engines before main tank fuel under normal conditions?
 - A) The center tank fuel pumps are selected ON before the main tank fuel pumps.
 - B) The center tank fuel pumps have higher output pressure than the main tank fuel pumps.
 - C) The main tank pumps are left in STANDBY until the EICAS message FUEL LOW CENTER is displayed.
 - D) Check valves prevent use of the main tank fuel before using center tank fuel.

- 4 What temperature is displayed below the Total fuel indication?
 - A) SAT (static air temperature).
 - B) TAT (total air temperature).
 - C) Fuel temperature.
 - D) Fuel freeze temperature.

- 5 Which of the following statements is true when the FUEL IMBALANCE message is displayed?
 - A) The fuel quantity indicator in the low tank turns amber.
 - B) A solid amber fuel imbalance pointer is displayed beside the tank with the low quantity.
 - C) A flashing amber fuel imbalance pointer is displayed beside the tank with the low quantity.
 - D) A solid white fuel imbalance pointer is displayed beside the tank with the low quantity.

HAB. B-777 HYDRAULICS

- 1 Following automatic deployment of the RAT due to system failures, what systems receive hydraulic power from the RAT?
- A) All primary flight control components.
 - B) Alternate gear extension system.
 - C) Normal brakes (after landing and airspeed below 60 kts).
 - D) Primary flight control components normally powered by the center hydraulic system.
- 2 What condition does not cause the amber Demand Pump FAULT light to illuminate?
- A) There is excessive demand pump fluid temperature.
 - B) Both C1 and C2 demand pump selector switches are ON.
 - C) There is low demand pump output pressure.
 - D) The demand pump is selected off.
- 3 In flight, what condition does not cause the RAT to deploy automatically?
- A) Both AC transfer busses are unpowered.
 - B) All three hydraulic system pressures are low.
 - C) All center hydraulic system primary and demand pumps fail.
 - D) Both engines are failed and the center hydraulic system pressure is low.
- 4 Which statement about the hydraulic systems is true?
- A) Flight control system components are distributed so that any one hydraulic system can provide adequate airplane controllability.
 - B) Hydraulic fluid is supplied to each hydraulic pump from the single central reservoir.
 - C) The demand pumps for the left and right systems are bleed air driven.
 - D) The left and right primary pumps are electric driven.
- 5 Which statement is true concerning center hydraulic system non-normal operation if quantity is sensed to be low and airspeed is greater than 60 knots?
- A) All are correct.
 - B) Leading edge slats are isolated and can operate in the primary mode.
 - C) Nose gear actuation and steering are reconnected.
 - D) Reserve brakes are isolated from the center system and remain operable.

HAB. B-777 LANDING GEAR

- 1 What causes the BRAKE SOURCE light to illuminate?
 - A) The alternate brake system is on battery power only.
 - B) The EICAS advisory message BRAKE SOURCE is inoperative.
 - C) Pressure is normal in the left hydraulic system.
 - D) Loss of the Right and Center/Reserve hydraulic systems.

- 2 What is the status of the parking brake if the PARKING BRAKE SET message is not displayed?
 - A) The APU RUNNING message will hide the PARKING BRAKE SET message.
 - B) It is set because the APU RUNNING message is displayed.
 - C) It cannot be set because the brake accumulator pressure is 1500 psi.
 - D) It is not set.

- 3 Which position does the AUTOBRAKE selector move to immediately after takeoff?
 - A) DISARM.
 - B) MAX AUTO.
 - C) RTO.
 - D) OFF.

- 4 What does the EICAS Message MAIN GEAR STEERING indicate?
 - A) Main gear is steering during a turn.
 - B) Main gear is not steering when commanded during a turn.
 - C) Main gear steering has reached a limit.
 - D) Main gear steering is unlocked when commanded to the center position.

- 5 Which statement about Nose Wheel and Aft Axle Steering is not correct?
 - A) Main gear aft axle steering is not possible using only rudder pedals.
 - B) The airplane is equipped with nose wheel steering and main gear steering aft axles on both main landing gear.
 - C) Nose wheel and aft axle steering are powered by the center/reserve hydraulic system.
 - D) Main gear aft axle steering automatically operates when the nose wheel steering angle exceeds 13 degrees.

HAB. B-777 WARNING SYSTEMS

- 1 What precaution should be taken if a tail strike occurs during takeoff?
 - A) The airplane should not be pressurized.
 - B) No special precautions are necessary.
 - C) Pressurize the airplane to a lower cabin altitude.
 - D) The flight may continue normally, but an entry must be made in the maintenance log.

- 2 What does the TCAS RA F/0 EICAS advisory message indicate?
 - A) TCAS is incapable of displaying RA traffic symbols on the First Officer's ND.
 - B) TCAS is incapable of displaying RA vertical guidance on the Captain's PFD.
 - C) TCAS is incapable of displaying RA traffic symbols on the Captain's ND.
 - D) TCAS is incapable of displaying RA vertical guidance on the First Officer's PFD.

- 3 How long will a WINDSHEAR warning on the PFD remain active?
 - A) Until the master warning light reset switch is pushed.
 - B) Until the GND PROX G/S caution light is pushed.
 - C) Until the landing gear are retracted.
 - D) Until windshear conditions are no longer detected.

- 4 What provides warning of an impending stall?
 - A) Left and right stick shakers.
 - B) Stall warning horn
 - C) GPWS STALL warning.
 - D) EICAS Message STALL.

HAB. B-777 LIMITATIONS

- 1 Under which of the following conditions is operation with assumed temperature reduced takeoff thrust is not permitted?
- A) Inoperative RTO mode.
 - B) Contaminated runways.
 - C) Inoperative anti-skid on two wheels.
 - D) A wet runway
- 2 Which of the following statements is correct regarding the ground wind limits for doors?
- A) 15 knots while opening or closing, 25 knots while open.
 - B) There are no ground wind Limits for doors.
 - C) 40 knots while opening or closing, 65 knots while open.
 - D) 38 knots while opening or closing, 45 knots while open.
- 3 What is the maximum crosswind component when basing landing weather minima on autoland operations?
- A) 38 knots.
 - B) 25 knots.
 - C) 30 knots.
 - D) 10 knots.
- 4 (777-200 F) What is the length of the Airplane from nose to tail of fuselage?
- A) 239 feet 9 inches (73.1 meters).
 - B) 199 feet 11 inches (60.9 meters).
 - C) 102 feet 5 inches (31.2 meters).
 - D) 209 feet 1 inches (63.73 meters).
- 5 ADIRU alignment must not be attempted at latitudes greater than which of the following?
- A) 68 degrees 15.75 minutes.
 - B) 78 degrees 14.75 minutes.
 - C) 58 degrees 16.75 minutes.
 - D) 87 degrees 13.75 minutes.
- 6 The Wing Span of the Airplane is:
- A) 206 feet 6 inches (63 meters).
 - B) 119 feet 11 inch (60.9 meters).
 - C) 239 feet 9 inches (73.1 meters).
 - D) 212 feet 7 inches (64.8 meters).

HAB. B-777 PERFORMANCE AND FLIGHT PLANNING

- 1 Which statement is most correct concerning landing and takeoff planning?
 - A) In landing planning, airplanes must be able to stop within 60% of the available runway.
 - B) The brake cooling schedule can be used for landing only.
 - C) The quick turnaround limit ensures sufficient brake energy capability in the next takeoff.
 - D) If the Landing Climb Limit Weight is exceeded for Flap 30, a Flap 20 landing must be planned.

- 2 FMC computed takeoff speeds (V SPEEDS) can be used for which performance condition?
 - A) When clearway or stopway adjustments are required to V1.
 - B) When the runway is contaminated.
 - C) When a brake is deactivated.
 - D) For balanced field length conditions.

- 3 Which of the following is not correct concerning long range cruise maximum operating altitude?
 - A) When thrust limiting is used a residual climb capability of 100 ft/min is available.
 - B) Above the maximum operating altitude, airspeed may be lost during level sustained turns using bank angles of approximately 21 degrees.
 - C) When thrust limiting is used a residual climb capability of 300 ft/min is available.
 - D) The maximum operating altitude considers the most restrictive of either thrust limiting or buffet limits.

- 4 Which of the following is the best description of the guideline for movement of the flap handle during flap retraction/extension?
 - A) When within 40 knots of the maneuver speed for the next flap setting.
 - B) When within 30 knots of the maneuver speed for the next flap setting.
 - C) When within 10 knots of the maneuver speed for the next flap setting.
 - D) When within 20 knots of the maneuver speed for the next flap setting.

HAB. B-777 NON-NORMAL PROCEDURES

- 1 Which one of the following is a condition for aborting an engine start ?
- A) No rise in oil temperature.
 - B) No oil pressure indication by initial EGT rise.
 - C) No increase in, or a very slow increase in N1 or N2 after EGT indication.
 - D) No N1 rotation before the engine start switch is moved to RUN.
- 2 What is the correct sequence of recall events for the [] FIRE ENG L,R EICAS message?
- A) If, after 30 seconds, FIRE ENG message remains displayed: # ENGINE FIRE. SWITCH ROTATE
 - B) # AUTOTHROTTLE ARM SWITCHOFF # THRUST LEVER# FUEL CONTROL SWITCHCUTOFF # ENGINE FIRE SWITCHPULL
 - C) If FIRE ENG message remains displayed: # ENGINE FIRE SWITCHROTATE TO OTHER BOTTLE.
 - D) # THRUST LEVER# AUTOTHROTTLE ARM SWITCH OFF # FUEL CONTROL SWITCHCUTOFF # ENGINE FIRE SWITCH PULL
- 3 During Rapid depressurization checklist recall steps, when is the passenger oxygen switch is activated?
- A) Cabin altitude is 12,500 feet or lower.
 - B) Cabin altitude is 10,000 feet.
 - C) Cabin altitude exceeds 15,000 feet.
 - D) Cabin altitude is uncontrollable.
- 4 Which statement about non-normal procedures is not correct?
- A) Amplified information included in [] brackets is displayed in the Electronic Checklist non-normal checklist when the reason for an item may not be self evident.
 - B) Reference items are actions to be accomplished while reading the checklist.
 - C) Checklists may contain both recall and reference items.
 - D) Recall items are critical steps that must be accomplished from memory and are preceded by the # symbol in the printed non-normal checklist.
- 5 When should the pilot flying call for the appropriate non-normal checklist?
- A) When all recall items are complete.
 - B) When the flight path is under control.
 - C) When the airplane is not in a critical stage of flight (such as takeoff or landing).
 - D) When all of these statements are completed.
- 6 What does the EICAS message WINDOWS indicate?
- A) Right side window is not closed and latched.
 - B) Left side window is not closed and latched.
 - C) The WINDOWS message does not exist. Only the EICAS messages WINDOW FL DECK L, R exist.

D) Left and right side windows are not closed and latched.

7 Both engines fail for no reason that you can see. What are the recall actions for DUAL ENG FAIL/STALL?

- A) #FUEL CONTROL SWITCHES (Both).....CUTOFF THEN RUN #RAM
AIR TURBINE SWITCH.....PULL
#AIRSPEED.....Above 250 kts
- B) #RAM AIR TURBINE SWITCH.....PUSH #FUEL CONTROL
SWITCHES.....CUTOFF, THEN RUN
- C) #FUEL CONTROL SWITCHES (Both).....CUTOFF, THEN RUN #RAM
AIR TURBINE SWITCH.....PUSH Push and hold for 1 second.
- D) #RAM AIR TURBINE SWITCH.....PUSH #FUEL CONTROL
SWITCHES.....CUTOFF, THEN RUN
#AIRSPEED.....Above 250 kts

HAB. B-777 FLIGHT INSTRUMENTS, DISPLAYS

- 1 What does the airplane symbol represent in ND Plan mode?
 - A) Predicted track.
 - B) Waypoint selected by prompt on the LEGS page.
 - C) Active waypoint.
 - D) Actual position and track along the flight plan route.

- 2 When using the Display Select Panel, what are the steps to select the status page on the left inboard display unit?
 - A) Select L INBD switch, then select ENG switch.
 - B) Select R INBD switch, then select STAT switch.
 - C) Select LWR CTR switch, then select STAT switch.
 - D) Select L INBD switch, then select STAT switch.

- 3 What Display Select Panel steps display the flight control synoptic on the right inboard display unit?
 - A) Select the FCTL switch, then select the R INBD switch.
 - B) Select the R INBD switch, then select the FCTL switch.
 - C) Select the R INBD switch, then select the CONT switch.
 - D) Select the L INBD switch, then select the FCTL switch.

- 4 What does the EICAS Message SGL SOURCE AIR DATA indicate?
 - A) A single source of display information is used by some or all display units.
 - B) Both PFDs are using the same source for flight director information.
 - C) Both PFDs are receiving air data from the same single channel source.
 - D) Both AIR DATA/ATTITUDE source switches are in the ALTN position.

- 5 What does the EICAS Message DISPLAY SELECT PNL indicate?
 - A) A single source of display information is used by some or all display units.
 - B) Left, center or right CDU control of the Display Control Panel is active.
 - C) The Display Control Panel is in use.
 - D) Both PFDs are using the same source of air data information.

- 6 Which statement is not correct about the Radio Altitude display on the PFD?
 - A) Indicates current ADIRS altitude below 2500 feet.
 - B) Displays radio altitude below 2500 feet AGL.
 - C) Turns amber when below radio altitude minimums.
 - D) The display box is highlighted in white for 10 seconds when passing below 1000 feet.

- 7 Which Display Select Panel switch displays the APU EGT?
 - A) FUEL (fuel system synoptic).
 - B) AIR (air systems synoptic).
 - C) STAT (status page).
 - D) ENG (secondary engine EICAS).

HAB. B-777 FLIGHT MANAGEMENT, NAVIGATION

- 1 Which of the following are data sources for the ADIRU?
 - A) AOA sensors and TAT probe only.
 - B) Static ports only.
 - C) Air data modules, AOA sensors, and TAT probe.
 - D) Air data modules only.

- 2 What is the altitude source for transponder altitude reporting when the ALT SOURCE selector is in the ALTN position?
 - A) ADIRU.
 - B) Air data modules.
 - C) The master FMC.
 - D) SAARU.

- 3 Which one of the following is inoperative with dual FMC failure?
 - A) Both CDUs.
 - B) MAP display.
 - C) VNAV.
 - D) LNAV.

- 4 What does the WXR FAIL ANT fault message indicate?
 - A) Weather returns will still display.
 - B) Weather returns will not display correctly.
 - C) There is a problem with the radar antenna.
 - D) Weather returns will not display or weather returns will display, but will be unreliable.

- 5 Which one of the following pages is available following dual FMC failure?
 - A) ALTN REF NAV DATA.
 - B) ALTN POS REF.
 - C) ALTN PERF INIT.
 - D) ALTN NAV LEGS.